

The following Notice to Mariners is published for general information

**Australia – Victoria
No. 306 – 2020
PORT OF MELBOURNE
SOUTH CHANNEL BEACON 14 REPLACED**

Date: 05 November 2020

Refers: **NtM 063 (T) /2020 refers and is cancelled.**

Details: Mariners are advised that, South Channel Beacon 14 (K2322-9) has been replaced and commissioned.

Consequently, the Temporary Buoy and corresponding virtual AIS marker has been removed.

Description	Latitude	Longitude	Characteristics
South Channel Beacon 14	38° 19.6613' S	144° 51.6226' E	FL (3) R.10s

For further information, please contact Melbourne Vessel Traffic Service on VHF Channel 12 or 9644 9700.

**Charts &
Publications**

affected: AU439144- (ENC cell number), AUS 158 & Admiralty List of Lights and Fog Signals NP83 (Volume K)

Further notice: No further notice will be issued.



**Roy Stanbrook
Acting Harbour Master
(as Kell Dillon on leave)**




This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au

PILE DETAILS

NOT TO SCALE



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au