

Australia – Victoria


No. – 359 (T) - 2021

PORT MELBOURNE PORT PHILLIP BAY ANCHORAGE S8 FOULED ANCHOR

- Date:** 23 November 2021
- Refers:** N/a.
- Details:** Mariners are advised of a submerged obstruction (Fouled Anchor) exist in the immediate vicinity of the S8 Anchorage area.
- Anchorage S8 is unavailable for anchoring until further notice.
- For further information please contact Melbourne Vessel Traffic Service on 96449700.
- Mariners are advised to navigate with additional caution in the vicinity of S8 Anchorage area.
- Charts & Publications affected:** AUS 155
- Further notice:** Further Notice will be issued



Kell Dillon
Harbour Master



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au