


The following Notice to Mariners is published for general information

Australia – Victoria**No. – 131 (T) - 2021****PORT MELBOURNE CHANNEL
BEACON 10 TEMPORARILY UNLIT**

- Date:** 08 April 2022
- Refers:** N/a
- Details:** Mariners are advised that, Port Melbourne Channel Beacon 10 (Fl(2) R4s 5m) in position 37° 53.187'S 144° 55.599'E, is temporarily unlit.
Virtual AIS **ATON TB10** has been deployed in this position.
For further information contact Melbourne VTS on 9644 9700.
Mariners are advised to navigate with additional caution when in the vicinity of Port Melbourne Channel Beacon 10.
- Charts & Publications affected** AUS 155
- Further notice:** Further Notice will be issued




**David Shennan
Harbour Master**



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
 The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website www.vicports.vic.gov.au