

The following Notice to Mariners is published for general information

Australia – Victoria**No. 269 – (T) - 2022****PORT MELBOURNE PORT PHILLIP
TEMPORARY WAVE MONITORING BUOY ADRIFT IN
PORT MELBOURNE WATERS****Date:** 01 August 2022**Refers:** NtM 419 (T) / 2021

Details: Mariners are advised that the wave monitoring buoy FL (Y) 2.5s established in the following position 38° 03.804' S, 144° 52.002' E is adrift, currently drifting east from its original position in Port Phillip Bay.

<i>Approximate Drift Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Characteristics</i>
Centre of Bay	38° 03.897' S	144° 53.248' E	FL (Y) 2.5s

For further information contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Mariners are advised to navigate with caution in the vicinity of the drifting buoy.

Charts & Publications affected AUS 143, (ENC) AU5MEL01

Further notice: Further notice will be issued.




**Warwick Laing
Harbour Master**

Wave monitoring buoy



Approximate position of adrift wave monitoring buoy and drift direction



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website www.vicports.vic.gov.au