

Australia – Victoria

No. 014 (T) - 2023

PORT OF MELBOURNE

PORT PHILLIP BAY

**TEMPORARY WAVE MONITORING BUOYS ESTABLISHED IN
PORT MELBOURNE WATERS AND LOCAL PORT OF PORT PHILLIP WATERS - AMENDED**

Date: 11 January 2023

Refers: NtM 436 (T) / 2022 and is hereby cancelled.

Details: Mariners are advised that a wave monitoring buoy originally established in the following position **38° 03.804' S 144° 52.002' E** has been recovered.

The following table of buoys established in the following positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or about November 2023.

<i>Approximate Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Characteristics</i>
<u>Port Melbourne Waters</u>			
Werribee	37° 59.100' S	144° 46.512' E	FL (Y) 2.5s
<u>Local Port of Port Phillip</u>			
Sandringham	37° 58.719' S	144° 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	FL (Y) 2.5s

For further information, contact Melbourne VTS on VHF Channel 12 or 9644 9700.

Mariners are advised to navigate with caution in the vicinity of the buoys.

Charts & Publications affected AUS 143, 155, 157
ENC AU5RIP01, AU5MEL01

**Further
notice:**

Further notice will be issued.



**David Tilsley
Deputy Harbour Master
(Navigation Services)**



WAVE MONITORING BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au