

The following Notice to Mariners is published for general information

Australia – Victoria

No. 412 (T) - 2023

**PORT OF MELBOURNE
SOUTH CHANNEL
BEACON 10 PILE REMOVED**

Date: 10 October 2023

Refers: NtM 272 (T) - 23 and is hereby cancelled.

Details: Mariners are advised that **South Channel Beacon 10** pile, previously located in charted position **38° 18.874' S 144° 48.860' E**, has been recovered.

A virtual aid to navigation **TB10** is established on the charted position of South Channel Beacon 10 until further notice.

A port hand lateral mark buoy is deployed as follows:

Buoy	Characteristics	Approximate Position
Port hand lateral mark	Fl.R.3S	38° 18.877' S 144° 48.875' E


For further information, please contact Melbourne VTS on VHF Channel 12 or call 9644 9700.

Charts & Publications affected: AUS 143
ENC AU5RIP01

Further notice: Further notice will be issued.



David Tilsley
Deputy Harbour Master
(Navigation Services)



NOT FOR NAVIGATION



TEMPORARY BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.