

The following Notice to Mariners is published for general information

Australia – Victoria

No. 316 - 2024

**PORT OF MELBOURNE
PORT PHILLIP BAY
SANDRINGHAM YACHT CLUB BUOY 5**

Date: 31 July 2024

Refers: NtM 199 (T) – 24 and is hereby cancelled

Details: Mariners are advised that **Sandringham Yacht Club Buoy 5 (SYC5), FI (4) Y 10s**, has been re-established in position **37° 58.810' S 144° 58.380' E**.


For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

Charts & Publications affected: AUS155
ENC AU5MEL01

Further notice: No further notice will be issued.



**Paul Fleming
Acting Deputy Harbour Master
Navigation Services**



NOT FOR NAVIGATIONAL USE



Sandringham Yacht Club Buoy 5

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.