

The following Notice to Mariners is published for general information

Australia – Victoria

No. 105 (T) - 2022

**PORT MELBOURNE
PORT MELBOURNE CHANNEL BEACON 1 RESIDUAL PILE
PROTRUSION REMOVED**

Date: 23 March 2022

Refers: NtM 088 (T) / 2022 and is hereby cancelled.

Details: Mariners are advised that Port Melbourne Channel Beacon 1 residual pile protrusion is now removed

The temporary starboard hand buoy with light characteristics Fl (2)G 4s and Virtual AIS ATON TB8 is still in place and active in position. $37^{\circ}55.6'S 144^{\circ} 55.7'E$

For further information, please contact Melbourne Vessel Traffic Service on VHF Channel 12 or 9644 9700.

Mariners are advised to navigate with caution in the vicinity of the Port Melbourne Channel Bcn 1.

Charts & Publications affected AUS 155

Further notice: Further Notice will be issued




**David Shennan
Harbour Master**



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
 The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au