

The following Notice to Mariners is published for general information

Australia – Victoria

No. 415 (T) - 2022

**PORT OF MELBOURNE
PORT PHILLIP BAY
EAST CARDINAL MARK BUOY - RECOVERED**

Date: 22 November 2022

Refers: NtM 412 (T) – 2022 and is hereby cancelled.

Details: Mariners are advised that the East Cardinal Mark Buoy Q (3) 10s originally established in the following position **38° 13.909'S 144° 50.614'E**, located to the north-east of the Pinnacle Channel Aquaculture Reserve, has been recovered.

Mariners are advised to navigate with additional caution in the vicinity of the Pinnacle Channel Aquaculture Reserve.

For further information, please contact Melbourne VTS on VHF Channel 12 or 9644 9700.


**Charts &
Publications
affected** AUS 143

**Further
notice:** Further notice will be issued.



**Warwick Laing
Harbour Master**

East Cardinal Mark Buoy - recovered



This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Victorian Notices to Mariners can be downloaded from the Victorian Ports Corporation (Melbourne) website
www.vicports.vic.gov.au