

Australia – Victoria

No. 365 (T) - 2023

**PORT OF MELBOURNE
PORT PHILLIP BAY**

TEMPORARY WAVE MONITORING BUOYS

Date: 8 September 2023

Refers: NtM 014 (T) – 2023 and is hereby cancelled.

Details: Mariners are advised the **Central** wave monitoring buoy (as identified in the below table) has been re-established in position **38° 03.811' S 144° 52.012' E**.

The following table of buoys established in the following positions, within the local Port of Port Phillip & Port of Melbourne waters, will remain in place until on or about November 2023.

<i>Approximate Location</i>	<i>Latitude</i>	<i>Longitude</i>	<i>Characteristics</i>
<u>Port Melbourne Waters</u>			
Werribee	37° 59.100' S	144° 46.512' E	FL (Y) 2.5s
Central	38° 03.811' S	144° 52.012' E	FL (Y) 2.5s
<u>Local Port of Port Phillip</u>			
Sandringham	37° 58.719' S	144° 59.730' E	FL (Y) 2.5s
Mt Eliza	38° 09.731' S	145° 03.261' E	FL (Y) 2.5s
Rosebud	38° 18.087' S	144° 52.364' E	FL (Y) 2.5s
Indented Head	38° 08.156' S	144° 45.184' E	FL (Y) 2.5s

For further information, contact Melbourne VTS on VHF Channel 12 or 9644 9700

Mariners are advised to navigate with caution in the vicinity of the buoys.

Charts & Publications affected:

AUS143, AUS155, AUS157

ENC AU5MEL01, AU5RIP01

Further notice: Further notice will be issued.



David Tilsley
Deputy Harbour Master
(Navigation Services)



WAVE MONITORING BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Ports Victoria Notices to Mariners can be downloaded from the website, www.vicports.vic.gov.au