

The following Notice to Mariners is published for general information

Australia – Victoria

No. 411 (T) - 2023

**PORT OF MELBOURNE
PORT MELBOURNE CHANNEL – SOUTH
BEACON 8 PILE REMOVED**

Date: 10 October 2023

Refers: NtM 346 (T) - 23 and is hereby cancelled.
NtM 385 (T) - 23 and is hereby cancelled.

Details: Mariners are advised that the **Port Melbourne Channel-South Beacon 8** pile, previously located in charted position **37° 53.856' S 144° 55.577' E**, has been recovered.

A virtual aid to navigation **TB12** has been repositioned on the charted position of Port Melbourne Channel-South Beacon 8 until further notice.

A port hand lateral mark buoy is deployed as follows:

Buoy	Characteristics	Approximate Position
Port hand lateral mark (without top mark)	Fl(2)R.4S	37° 53.829' S 144° 55.587' E


For further information, please contact Melbourne VTS on VHF Channel 12 or call 9644 9700.

**Charts &
Publications
affected:** AUS 155
ENC AU5MEL01

Further notice: Further notice will be issued.




David Tilsley
Deputy Harbour Master
(Navigation Services)



NOT FOR NAVIGATION

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic). The requirements of section 232(2) have been taken into account.

Ports Victoria Notices to Mariners can be downloaded from the website, www.vicports.vic.gov.au



TEMPORARY BUOY

This notice is a direction of the Harbour Master pursuant to section 232 of the *Marine Safety Act 2010* (Vic)
The requirements of section 232(2) have been taken into account.

Ports Victoria Notices to Mariners can be downloaded from the website, www.vicports.vic.gov.au