

Australia – Victoria

No. 485 - 2024

PORT OF MELBOURNE PORT MELBOURNE CHANNEL BEACON REPLACEMENT WORKS COMPLETED

Date: 13 November 2024

Refers: NtM 358 (T) – 24 and is hereby cancelled
NtM 411 (T) – 23 and is hereby cancelled

Details: Mariners are advised that beacon replacement works undertaken for **Port Melbourne Channel beacons 3, 7, 8, 9, 70, 73, 74, 76, 78 and 79** are now completed and all restrictions for works have been lifted.

The old beacon piles and topsides have been removed and replaced by new beacon piles and topsides with original beacon light characteristic details as follows:

Beacon	ADLL Number	Characteristic	New Position
3	K 2337-3	Fl (2) G.4s	37° 55.071' S 144° 55.683' E
7	K 2338-18	Fl (2) G.4s	37° 53.855' S 144° 55.723' E
8	K 2338-17	Fl (2) R.4s	37° 53.852' S 144° 55.577' E
9	K 2338-2	Fl (2) G.4s	37° 53.187' S 144° 55.745' E
70	K 2338-45	Fl (2) R.4s	37° 52.065' S 144° 55.657' E
73	K 2338-6	Fl (2) G.4s	37° 51.722' S 144° 55.772' E
74	K 2339	Fl (2) R.4s	37° 51.299' S 144° 55.682' E
76	K 2339-2	Fl (2) R.4s	37° 51.104' S 144° 55.631' E
78	K 2339-3	Fl (2) R.4s	37° 50.909' S 144° 55.476' E
79	K 2339-24	Fl (2) G.4s	37° 50.860' S 144° 55.979' E

A port hand lateral mark buoy previously deployed in position 37° 53.829' S 144° 55.587' E has been removed and is permanently withdrawn. Virtual aid to navigation **TB12** has been deactivated and is permanently discontinued.

For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au.

**Charts &
Publications
affected:**

AUS 155
ENC AU5MEL01
Admiralty Digital List of Lights - Area 7 - Volume K

Further notice: No further notice will be issued.



**Sheldon Rodrigues
Acting Harbour Master**