

The following Notice to Mariners is published for general information

Australia – Victoria

No. 518 (T) - 2024

**PORT OF MELBOURNE
YARRAVILLE 5**

PILE REMEDIATION WORKS EXTENDED

Date: 25 November 2024

Refers: NtM 213 (T) - 24 and is hereby cancelled

Details: Mariners are advised that pile remediation works, involving diving operations, being undertaken at **Yarraville 5 berth** are extended **until further notice**.

Works will be conducted around shipping, **Monday to Sunday** from **0700 hrs** to **1700 hrs**.

The following conditions will apply for **works**:

1. When **Yarraville 5 berth** is occupied, berthed vessel to be **notified by works contractor**.
2. **30 minutes** prior to **arrival** and **departure** of a **commercial vessel (SOLAS)** to **Yarraville 5 berth**, including arrival/departure of the bunker vessel to a vessel at berth, the following applies:
 - **Diving operations and works to cease**
 - **Personnel and work vessels / barges to vacate area**
3. **30 minutes** prior to the passing of **commercial vessels (SOLAS)** within **50m of diving operations**:
 - **Diving operations to cease**
4. **No diving operations or hot works** will take place when **bunkering** is being conducted at **Yarraville 5 berth**.

Clear access for vessel, cargo, and mooring operations, both landside and waterside will be maintained during works.

Restrictions for passing **domestic commercial vessels** and **recreational vessels** during **works**:

- **Minimum wake and wash**
- **Minimum passing distance of 50m**

Dive vessels will display International Code flag Alpha during diving operations.

Works supervisor can be contacted on **0486 024 141**. Vessels supporting works can be contacted on VHF Channel 12.

Mariners are advised to navigate with additional caution in the vicinity of Yarraville 5 berth during works.

For further information, please email the Navigation Services department at NavigationServices@ports.vic.gov.au or contact Melbourne VTS on 9644 9700 / VHF Channel 12.

**Charts &
Publications
affected:**

ENC AU5MEL01

Further notice:

Further notice will be issued.



**David Tilsley
Deputy Harbour Master
Navigation Services**